


6.302 3/31/20, 4/1/20
Feed Back Systems

(7)



$X_{dist} = 0$

$Y = G X$

$G(s) = \frac{K(s)H(s)}{1 + K(s)H(s)}$

$X = 0$

$Y = KH(X - Y) + X_{dist}$

$Y = \frac{1}{1 + KH} X_{dist} G_{dist}$

IF $|K(j\omega)H(j\omega)| \gg 1$

$G(j\omega) \approx 1 \leftarrow$ Good Tracking

$G_{dist}(j\omega) \approx 0 \leftarrow$ Good Disturbance Rejection

(2)

IF $K(j\omega)H(j\omega) \approx -1$

$$G(j\omega) = \frac{\textcircled{-1}^{KH}}{1 + (-1)^{KH}} \Rightarrow \infty$$

$$G_{\text{dist}}(j\omega) = \frac{1}{1 + (-1)} \Rightarrow \infty$$

So if $|K(j\omega)H(j\omega)| = 1$ and $\neq K(j\omega)H(j\omega) = -1$

Tracking & Disturbance rejection are terrible!

And the closer $K(j\omega)H(j\omega)$ is to -1
the worse the tracking and disturbance rejection

But Just because $K(j\omega)H(j\omega)$ is always far from -1 , no guarantee of stability for G

Sinusoidal Steady State exists only if system is stable

Why? Given $x(t) = e^{j\omega t}$

$y(t) = G(j\omega)e^{j\omega t}$ for large t only if G is stable

$G(j\omega)$ is physically meaningless if G is unstable

Example

Good phase margin necessary but not sufficient

3

$$H_{prop} = \frac{200}{(s+10)(s)(s)} \quad K=1$$

$$G = \frac{KH}{1+KH}$$

$$= \frac{200}{(s+10)(s)(s) + 200}$$

$$= \frac{200}{s^3 + 10s^2 + 200}$$

At $\omega = 4.3 \text{ rad/sec}$

$$|K A_{prop}(j\omega)| = \left| \frac{200}{(j\omega+10)(j\omega)(j\omega)} \right|$$

$$= \left| \frac{200}{-j\omega^3 - 10\omega^2} \right| = \left| \frac{200}{-185 - 80j} \right|$$

$$\approx 1$$

4B

$$\angle KH(j\omega) = \angle \left(\frac{200}{-185 - 80j} \right) = -203^\circ \neq -180^\circ$$

$$\omega = 4.3 \text{ rad/sec}$$

($\approx \omega_{\text{unity}}$)

at $\omega = 4.3$ $|KH(j\omega)| \approx 1$ $\angle KH(j\omega) = -203^\circ$

Satisfies
phase
margin
conditions

$$\rightarrow KH \neq -1$$

But poles($G(s)$) are unstable!

$$\text{poles}(G) = \underbrace{0.75 \pm 4.1j}_{\text{Real positive}}, -11.5$$

Real
positive


$G(s)$ is unstable

Good phase margin is a necessary
condition for good control
not a sufficient condition!

5

Example


$$H(s) = \frac{100}{(s+1)(s+100)}$$



Design controller for $K_p = 10, 100$ & $10,000$
What is the phase margin?

6


$K_p = 10$



$K_p = 10$, $H(s) = 1$, phase margin $\approx 90^\circ$

7

$K_p = 100$



For $K_p = 100$ phase margin $\approx 4.5^\circ$
okay but could be better. Lead? Lag?

Idea 1

Place a lead compensator with $q = -100$ $p = -1000$

Return to Later!

$$K(s) = K_p \frac{p}{q} \left(\frac{s-q}{s-p} \right) = 100 \frac{s+100}{s+1000}$$

$$KH(s)H(s) = 100 \cdot \frac{100}{(s+1)(s+100)} \cdot \frac{(s+100)}{s+1000} = \frac{10000}{(s+1)(s+1000)}$$


→ But Pole-Zero Cancellation Problematic!

8

$K_H \gg 1$!
Good Tracking!
Good dist Reject!

$K_p = 10000$

$20 \log |K_H(\omega)|$



For $K = 10000$

phase margin $\approx 0^\circ$
Bad, almost unstable

Idea 1

Place a lead with
 $q = -1000$ $p = -10000$

$K(s)H(s) = 100,000 \left(\frac{s+1000}{s+10000} \right) \left(\frac{100}{(s+1)(s+100)} \right)$


9

Actual Margin

$$G(s)H(s) = 10^5 \left(\frac{s + 10^3}{s + 10^4} \right) \left(\frac{100}{(s+1)(s+100)} \right)$$

little shift in compensator changes

in unity (from ≈ 1000)
 For $H(s) = \frac{10^5}{(s+1)(s+100)}$



phase margin $\approx 45^\circ$


near 45° predicted

$K = 10,000$
Too Soon

(10)

$$H_c(s) = 10 \left(\frac{s+100}{s+1000} \right)$$

Zero at too
low a frequency




Actual Top Soon

$$H_e(s) = 10 \frac{s+100}{s+1000}$$

(11)


Unit - III ud (a) III (a) u/s), r III - 10 ucy (a) u.u.u.u.u.u



13


Actual Too Late $H_c(s) = 10 \frac{s+10000}{s+100000}$

III - III ud (ar III ra/s), III - IV-3 ug (ar IV-3)



14


Lead a little late $\rightarrow H_c(s) = 10 \frac{(s + 3900)}{(s + 39000)}$



2nd Idea

$$K(s) = 10000 \cdot \frac{1}{100(s+0.1)} \cdot \frac{1}{(s+10)}$$

Lag to drop gain and reduce ω_{unity} . To reduce ω_{unity} to 100, reduce gain by 40dB!




$$K(s)H(s) = \underbrace{10000}_{K_p} \frac{1}{100} \frac{(s+10)}{(s+0.1)} \left(\frac{100}{(s+1)(s+100)} \right)$$

Actual Lag

$$K(s) = 10^4 \frac{1}{100} \left(\frac{s+10}{s+0.1} \right)$$

16




Unit - Unit (rad/s), Unit - Unit (rad/s)

Lag Too Soon

$$K(s) = \frac{10^4}{100} \left(\frac{s+1}{s+9.91} \right)$$

17

UNIT - IIII UP (a) IIII (a) u/s) , IIII - 0.1.0 ucy (a) 1.0.0 1.0




Lag Way Too Soon

$$K(s) = \frac{10^4}{100} \left(\frac{s+0.1}{s+0.001} \right)$$

18

Unit - Unit (rad/s), Unit - Unit (rad/s)



Observations

1) Lead compensators can be used to increase phase margin without reducing gain at frequencies below ω_{unity} .

$$|K H_{lead}(j\omega) H(j\omega)| \approx |K H(j\omega)| \quad \omega < \omega_{unity}$$

2) Lead zero and pole must surround ω_{unity} to be effective (Though $\omega_{unity}^{compensated}$ may not equal $\omega_{unity}^{uncompensated}$)

3) If the phase margin is acceptable at frequencies below ω_{unity} , low-frequency lag can be used to reduce the ω_{unity} .

4) For many systems H_1 , if a lag with pole p and zero q produces a given phase margin, then any $\alpha p, \alpha q$, $\alpha < 1$, will NOT reduce the phase margin.

Usual Mechanical Example


20

$$H(s) = \frac{Y(s)}{X(s)} = \frac{(-p)}{s^2(s-p)}$$

Force to position


command \rightarrow force

$\angle H(j\omega)$



$|H(j\omega)|$


$\delta = P_c^2$
Example



1) Lead Alone Could work

pole-zero separation = 100!

$$H_c(s) = 100 \left(\frac{s + p_c/10}{s + 10p_c} \right)$$



Can you draw the diagrams for $20 \log |H_c(j\omega) H(j\omega)|$ and $\angle H_c(j\omega) H(j\omega)$?


If $K_p = 1000$

with
$$\underbrace{(K_p \cdot H_c(s))}_{K(s)} \cdot \frac{-p_c^3}{s^2(s-p_c)}$$

Can $H_c(s)$ be a lead compensator?
and achieve a phase margin
near 45° ?

Answer: No! Phase margin at unity $\approx -90^\circ$

Maximum lead
 phase boost
 $= 90^\circ!$



$20 \log |KH(j\omega)|$

160
120
80
40
0db

(23)

For $K=1000$ Case Combine Lead and Lag

Drops
the
gain
to make
 $\omega_{unity} = P_c$

$$H_{lag}(s) = \frac{1}{1000} \left(\frac{s - P_c/100}{s - P_c/100,000} \right)$$

"Bumps"
the
phase
UP
at ω_{unity}

$$H_{lead}(s) = 100 \left(\frac{s - P_c/10}{s - 10P_c} \right)$$

Can you plot the diagrams?