




$$\underline{X_{dist} = 0}$$

$$Y = G X$$

$$G(s) = \frac{K(s)H(s)}{1 + K(s)H(s)}$$

$$\underline{X = 0}$$

$$Y = KH(X - Y) + X_{dist}$$

$$Y = \frac{1}{1 + KH} X_{dist} \quad G_{dist}$$

$$\underline{\text{If}} \quad |K(j\omega)H(j\omega)| \gg 1$$

$$G(j\omega) \approx 1 \quad \leftarrow \text{Good Tracking}$$

$$G_{dist}(j\omega) \approx 0 \quad \leftarrow \text{Good Disturbance Rejection}$$

(2)

IF $K(j\omega)H(j\omega) \approx -1$

$$G(j\omega) = \frac{\overset{KH}{\textcircled{-1}}}{1 + (-1)} \Rightarrow \infty$$

$$G_{\text{dist}}(j\omega) = \frac{1}{1 + (-1)} \Rightarrow \infty$$

So if $|K(j\omega)H(j\omega)| = 1$ and $\angle K(j\omega)H(j\omega) \neq \pm 180^\circ$

Tracking & Disturbance rejection are terrible!

And the closer $K(j\omega)H(j\omega)$ is to -1
the worse the tracking and disturbance rejection

But Just because $K(j\omega)H(j\omega)$ is always far from -1 , no guarantee of stability for G

Sinusoidal Steady State exists only if system is stable

Why? Given $x(t) = e^{j\omega t}$
 $y(t) = G(j\omega)e^{j\omega t}$ for large t
only if G is stable
 $G(j\omega)$ is physically meaningless if G is unstable

Example

Good phase
margin necessary
but not sufficient

3

$$H_{prop} = \frac{200}{(s+10)(s)(s)} \quad K=1$$

$$G = \frac{KH}{1+KH}$$

$$= \frac{200}{(s+10)(s)(s) + 200}$$

$$= \frac{200}{s^3 + 10s^2 + 200}$$

At $\omega = 4.3 \text{ rad/sec}$

$$|K A_{mp}(j\omega)| = \left| \frac{200}{(j\omega+10)(j\omega)(j\omega)} \right|$$

$$= \left| \frac{200}{-j\omega^3 - 10\omega^2} \right| = \left| \frac{200}{-185 - 80j} \right|$$
$$\approx 1$$

(4B)

$$\angle KH(j\omega) = \angle \frac{200}{(-185 - 80j)} = -203^\circ \neq -180^\circ$$

$$\omega = 4.3 \text{ rad/sec} \\ (\approx \omega_{\text{unity}})$$

$$\text{at } \omega = 4.3 \quad |KH(j\omega)| \approx 1 \quad \angle KH(j\omega) = -203^\circ$$

Satisfies
phase
margin
conditions

$$\rightarrow KH \neq -1$$

But poles($G(s)$) are unstable!

$$\text{poles}(G) = \underbrace{0.75}_{\text{Real}} \pm 4.1j, -11.5$$

Real
positive


$G(s)$ is unstable

Good phase margin is a necessary
condition for good control
not a sufficient condition!

5

Example


$$H(s) = \frac{100}{(s+1)(s+100)}$$



Design controller using $K_p = 10, 100 \text{ \& } 10,000$
 What is the phase margin?


6

$K_p = 10$



7

$K_p = 100$



For $K_p = 100$ phase margin $\approx 4.5^\circ$
 okay but could be better. Lead? Lag?

Idea 1

Place a lead compensator
 with $sz = q = -100$, $sp = p = -1000$

$$K(s) = K_p \frac{p}{a} \left(\frac{s-q}{s-p} \right) = K_p 10 \frac{s+100}{s+1000}$$

$$KH(s)H(s) = 100 \cdot \frac{100}{(s+1)(s+100)} \cdot \frac{(s+100)}{s+1000} = \frac{10000}{(s+1)(s+1000)}$$

→ But Pole-Zero Cancellation Problematic!

Return to Later!


$$K_p = 10000$$

$$KH \gg 1!$$

Good Tracking!

Good dist Reject!

8



For $K=10000$

phase margin $\approx 0^\circ$

Bad, almost unstable

Idea 1

Place a lead with

$$q = -1000$$

$$p = -10000$$


$$K(s)H(s) = 100000 \left(\frac{s+1000}{s+10000} \right) \left(\frac{100}{(s+1)(s+10)} \right)$$

9

Actual Margin

$$K(s)H(s) = 10^5 \left(\frac{s + 10^3}{s + 10^4} \right) \left(\frac{100}{(s+1)(s+100)} \right)$$

compensator zeroes
little shift



$$= K(s)|H(s)|$$

$s=0$

$$\omega_{unity} \approx 1260$$

phase margin $\approx 45^\circ$

near 45°
predicted


in ω_{unity} (from ≈ 1000)
for $H(s) = \frac{10^5}{(s+1)(s+100)}$

$K = 10,000$
Too Soon

(10)

$$H_c(s) = 10 \left(\frac{s+100}{s+1000} \right)$$


Zero at too
low a frequency



(11)


Actual Too Soon

$$H_e(s) = 10 \frac{s+100}{s+1000}$$




13

Actual Too Late $H_c(s) = 10 \frac{s+10000}{s+100000}$



14


Lead a little late $\rightarrow H_c(s) = 10 \frac{(s + 3900)}{(s + 39000)}$



2nd Idea

$$K(s) = 10000 \cdot \frac{1}{100} \frac{(s+10)}{(s+0.1)}$$

Lag to drop gain and reduce ω_{unity} . To reduce ω_{unity} to 100, reduce gain by 40dB!




$$K(s)H(s) = \underbrace{10000}_{K_p} \frac{1}{100} \frac{(s+10)}{(s+0.1)} \left(\frac{100}{(s+1)(s+100)} \right)$$

Actual Lag

$$K(s) = 10^4 \frac{1}{100} \left(\frac{s+10}{s+0.1} \right)$$

(16)




Unit - Unit (rad/s), Unit - Unit (rad/s)

17

Lag Too Soon


$$K(s) = \frac{10^4}{100} \left(\frac{s+1}{s+9.91} \right)$$



18

Lag Way Too Soon

$$K(s) = \frac{10^4}{100} \left(\frac{s+0.1}{s+0.001} \right)$$



Observations

- 1) Lead compensators can be used to increase phase margin without reducing gain at frequencies below ω_{unity} .

$$|K H_{lead}(j\omega) H(j\omega)| \approx |K H(j\omega)| \quad \omega < \omega_{unity}$$

- 2) Lead zero and pole must surround ω_{unity} to be effective (Though $\omega_{unity}^{compensated}$ may not equal $\omega_{unity}^{uncompensated}$)

- 3) If the phase margin is acceptable at frequencies below ω_{unity} , low-frequency lag can be used to reduce the ω_{unity} .

- 4) For many systems H , if a lag with pole p and zero q produces a given phase margin, then any $\alpha p, \alpha q$, $\alpha < 1$, will NOT reduce the phase margin.

Usual Mechanical Example

(20)

$$H(s) = \frac{\gamma(-p_c)}{s^2(s-p_c)}$$

Force
to
position


command $\rightarrow$ Force

$\angle H(j\omega)$

-180

-270

-45° phase margin



$|H(j\omega)|$

$$\gamma = p_c^2$$

Example

120

100

80

60

40

20

0db

-60

40db/decade


Unity

60db/decade

1) Lead Alone Could work

pole-zero
separation
= 100!

$$H_c(s) = 100 \left(\frac{s + p_c/10}{s + 10p_c} \right)$$




Can you draw the diagrams for
 $20 \log |H_c(j\omega) H(j\omega)|$ and $\angle H_c(j\omega) H(j\omega)$?

If $K_p = 1000$

with $\underbrace{K_p \cdot H_c(s)}_{K(s)} \cdot \frac{-P_c^3}{s^2(s-P_c)}$

Can $H_c(s)$ be a lead compensator?
and achieve a phase margin
near 45° ?

Answer: No! Phase margin at unity $\approx -90^\circ$



(23)

For $K=1000$ Case

Combine Lead and Lag

Drops
the
gain
to make
 $\omega_{unity} \approx P_c$

$$\left\{ H_{lag}(s) = \frac{1}{1000} \left(\frac{s - P_c/100}{s - P_c/100,000} \right) \right.$$

"Bumps"
the
phase
up
at ω_{unity}

$$\left\{ H_{lead}(s) = 100 \left(\frac{s - P_c/10}{s - 10P_c} \right) \right.$$

Can you plot the diagrams?